

COPY



UNITED STATES
ENVIRONMENTAL PROTECTION AGENCY

REGION 5
RCRA ACTIVITIES
P.O. BOX A3587
CHICAGO, ILLINOIS 60690

NOV 12 1991

NOV 13 1991 JW

CUSTOM BLENDED OILS INC
ATTN DANIELS HADUCH
P O BOX 1041
PEOTONE IL 60468

RE: EPA ID #: ILD 069 503 944

In response to your request of 10/25/91 the following
information has been updated:

Name of installation to	CUSTOM BLENDED OILS, INC
Location of installation to	31755 S RATHJE RD
Installation mailing address to	PO BOX 1041
Installation contact to	DANIEL HADUCH
Installation Legal Owner to	LORENE WINKLE
Generator status to	VERY SMALL QUANTITY
Addition waste code	D001 AND D002

If you have any questions, please contact me at (312) 886-6173.

Sincerely,

Sharon Kiddon
RCRA Notifications Coordinator
Waste Management Division

cc: State Agency
File

NOV 12 1991
K

Please refer to the Instructions for Filing Notification before completing this form. The information requested here is required by law (Section 3010 of the Resource Conservation and Recovery Act).



Notification of Regulated Waste Activity

United States Environmental Protection Agency

Date Received
(For Official Use Only)

I. Installation's EPA ID Number (Mark 'X' in the appropriate box)

☐ A. First Notification

☒ B. Subsequent Notification (complete form C)

C. Installation's EPA ID Number

I L D 0 6 9 5 0 3 9 4 4

II. Name of Installation (Include company and specific site name)

C U S T O M B L E N D E D O I L S I N C.

III. Location of Installation (Physical address not P.O. Box or Route Number)

Street

3 1 7 5 5 S. R A T H J E R O A D

Street (continued)

City or Town

P E O T O N E

State

ZIP Code

I L

6 0 4 6 8 - 1 0 4 1

County Code

County Name

1 9 7 W I L L

IV. Installation Mailing Address (See Instructions)

Street or P.O. Box

P. O. B O X 1 0 4 1

City or Town

P E O T O N E

State

ZIP Code

I L

6 0 4 6 8 - 1 0 4 1

V. Installation Contact (Person to be contacted regarding waste activities at site)

Name (last)

H A D U C H

(first)

D A N I E L

Job Title

E N V C O O R D

Phone Number (area code and number)

3 1 2 - 8 2 1 - 4 7 4 7

VI. Installation Contact Address (See Instructions)

A. Contact Address

Location Mailing

☐ ☒

B. Street or P.O. Box

City or Town

P E O T O N E

State

ZIP Code

I L

6 0 4 6 8 - 1 0 4 1

VII. Ownership (See Instructions)

A. Name of Installation's Legal Owner

L O R E N E W I N K L E

Street, P.O. Box, or Route Number

P. O. B O X 1 0 4 1

City or Town

P E O T O N E

State

ZIP Code

I L

6 0 4 6 8 - 1 0 4 1

Phone Number (area code and number)

7 0 8 - 2 5 8 - 6 8 8 1

U. Land Type

P

C. Owner Type

P

D. Change of Owner Indicator

Yes X No

(Date Changed)

Month Day Year

0 2 0 1 9 0

ID - For Official Use Only

VIII. Type of Regulated Waste Activity (Mark 'X' in the appropriate boxes. Refer to instructions.)

A. Hazardous Waste Activity

1. Generator (See instructions)
- ☐ a. Greater than 1000 kg/mo (2,200 lbs.)
- ☐ b. 100 to 1000 kg/mo (220 - 2,200 lbs.)
- ☒ c. Less than 100 kg/mo (220 lbs.)
2. Transporter (Indicate Mode in boxes 1-5 below)
- ☐ a. For own waste only
- ☒ b. For commercial purposes
- Mode of Transportation
- ☐ 1. Air
- ☐ 2. Rail
- ☒ 3. Highway
- ☐ 4. Water
- ☐ 5. Other - specify _____
- ☐ 3. Treater, Storer, Disposer (at installation)
Note: A permit is required for this activity; see instructions.
4. Hazardous Waste Fuel
- ☐ a. Generator Marketing to Burner
- ☐ b. Other Marketers
- ☐ c. Burner - Indicate device(s) - Type of Combustion Device
- ☐ 1. Utility Boiler
- ☐ 2. Industrial Boiler
- ☐ 3. Industrial Furnace
- ☐ 5. Underground Injection Control

B. Used Oil Fuel Activities

1. Off-Specification Used Oil Fuel
- ☐ a. Generator Marketing to Burner
- ☒ b. Other Marketer
- ☐ c. Burner - Indicate device(s) - Type of Combustion Device
- ☐ 1. Utility Boiler
- ☐ 2. Industrial Boiler
- ☐ 3. Industrial Furnace
- ☒ 2. Specification Used Oil Fuel Marketer (or On-site Burner) Who First Claims the Oil Meets the Specification

IX. Description of Regulated Wastes (Use additional sheets if necessary)

- A. Characteristics of Nonlisted Hazardous Wastes. Mark 'X' in the boxes corresponding to wastes your installation handles. (See 40 CFR Parts 261.20 - 261.24)

characteristics of nonlisted hazardous

1. Ignitable (D001) ☒
2. Corrosive (D002) ☒
3. Reactive (D003) ☐
4. EP Toxic (D000) ☐
- (List specific EPA hazardous waste number(s) for the EP Toxic contaminant(s))

number(s) for the EP Toxic contaminant(s))

- B. Listed Hazardous Wastes. (See 40 CFR 261.31 - 33. See instructions if you need to list more than 12 waste codes.)

1	2	3	4	5	6
7	8	9	10	11	12

- C. Other Wastes. (State or other wastes requiring an I.D. number. See instructions.)

1	2	3	4	5	6

X. Certification

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fines and imprisonment.

Signature

Lorene Winkle

Name and Official Title (type or print)

Lorene Winkle, President

Date Signed

September 26, 1991

XI. Comments

Note: Mail completed form to the appropriate EPA Regional or State Office. (See Section III of the booklet for addresses.)

Please print or type with ELITE type (12 characters per inch) in the unshaded areas only

Form Approved, OMB No. 2950-0020-10-31-01
GSA No. 02-00-EPA-01

Please refer to the instructions for Filing Notification before completing this form. The information requested here is required by law (Section 3010 of the Resource Conservation and Recovery Act).



Notification of Regulated Waste Activity

United States Environmental Protection Agency

Date Received
(For Office Use Only) 09/19/90

EPA, REGION V
SWRL RMS

I. Installation's EPA ID Number (See Instructions)

☒ A. First Notification ☐ B. Subsequent Notification (complete form C)
EPA ID Number ILD984805309

II. Name of Installation (Include company name, address and name)

CUSTOM CLEANING SYSTEMS INC

III. Location of Installation (Include street, city, state and ZIP Code)

Street: 31755 S RATHJE RD B

City or Town: PEOTONE IL 60468

County Code: 197 WIL

IV. Installation Mailing Address (See Instructions)

Street or P.O. Box: P O BOX 1041

City or Town: PEOTONE IL 60468

V. Installation Contact Person (See Instructions)

Name (last): HADUCH DANIEL

Job Title: ENV COORDINATOR 312-821-4747

VI. Installation Contact Address (See Instructions)

A. Contact Address (See Instructions)

City or Town: PEOTONE IL 60468

VII. Ownership (See Instructions)

A. Name of Installation's Legal Owner: LORENE WINKLE

Street, P.O. Box: P O BOX 1041

City or Town: PEOTONE IL 60468

Phone Number (area code and number): 708-253-6881

Change of Owner Indicator: Yes No

VIII. Type of Regulated Waste

1. General (See instructions)

- ☒ a. Greater than 1000 lbs (2,200 lb)
☐ b. 100 to 1000 lbs (220 - 2,200 lb)
☐ c. Less than 100 lbs (220 lb)

2. Transporter (Indicate mode in boxes 3-6)

A. For Air Transport

B. For Surface Transport

Mode of Transport

- ☐ 1. Air
☐ 2. Rail
☒ 3. Highway
☐ 4. Water
☐ 5. Other

IX. Description of Regulated Waste (See instructions)

A. Characteristics of Nonlisted Hazardous Wastes. Mark 'X' in the boxes corresponding to the characteristics of nonlisted hazardous wastes your installation handles. (See 40 CFR Parts 261.20 - 261.24)

Flammable
(2001)

☐
☒
☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

B. Listed Hazardous Wastes. (See 40 CFR 261.31 - 33. See instructions if you need to list more than 12 waste codes.)

1	2	3	4	5	6
F 0 0 1	F 0 0	F 0 0 3	F 0 0 4	F 0 0 5	


C. Other Wastes. (State or other wastes requiring an I.D. number. See instructions.)

1	2	3	4	5	6

X. Certification

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this, and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fines and imprisonment.

Signature



Name and Official Title (type or print)

LORENE WINKLE, PRESIDENT

Date Signed

Sept 17, 1990

XI. Comments

Note: Mail completed form to the appropriate EPA Regional or State Office. (See Section III of the booklet for addresses.)

CONVERSATION RECORD

TIME

2:00 PM

DATE

2/2/90

TYPE

☐ VISIT

☐ CONFERENCE

☒ TELEPHONE

☐ INCOMING

☒ OUTGOING

Location of Visit/Conference:

NAME OF PERSON(S) CONTACTED OR IN CONTACT WITH YOU

GARY KING

ORGANIZATION (Office, dept., bureau, etc.)

IEPA

TELEPHONE NO:

217-782-5544

SUBJECT

CUSTOM BLENDED, OILS, INC. 3008(a) order

ROUTING

NAME/SYMBOL

INT

SUMMARY

→ I called Gary to inform him that U.S. EPA is in the process of drafting a 3008(a) for this facility for WAF violations & that we've included violations under 262 & 263 in the Complaint. State authorized for enf these regs.

→ Gary said State doesn't have a problem w/ us including specific violations under 262 & 263.

→ He said to copy him on 3008(a)(2) notice letter & if he has any questions he'll call at that time.

ACTION REQUIRED

NAME OF PERSON DOCUMENTING CONVERSATION

SIGNATURE

Allen T. Wojtas

DATE

2/2/90

ACTION TAKEN

SIGNATURE

TITLE

DATE

ATTENTION ILLINOIS FACILITIES:

IF YOUR COMPANY IS LOCATED IN ILLINOIS YOU MUST SEND YOUR NOTIFICATION
TO THE FOLLOWING ADDRESS:

Illinois Environmental Protection Agency
Division of Land Pollution Control
2200 Churchill Road, #24
Springfield, Illinois 62706

ATTN: JIM PIERCE

yes

APPENDIX B

EPA HAZARDOUS WASTE NUMBERS FOR WASTE STREAMS COMMONLY GENERATED BY SMALL QUANTITY GENERATORS

The Environmental Protection Agency recognizes that generators of small quantities of hazardous waste, many of which are small businesses, may not be familiar with the manner in which hazardous waste materials are identified. This Appendix has been assembled to aid 100-1000 kg/mo small quantity generators in determining the EPA Hazardous Waste Numbers for their wastes. These numbers are needed to complete the "Notification of Hazardous Waste Activity," Form 8700-12.

This Appendix contains lists of EPA Hazardous Waste Numbers for each waste stream identified in Table 2 in Chapter 1 of the handbook. Note that acutely hazardous wastes are identified with an asterisk (*).

To Use This Appendix

1. Locate your business type in Table 2 in Chapter 1. This will help you to identify the waste streams common to your activities.
2. Find each of the waste streams that you identified in Table 2 in the more detailed descriptions in this Appendix. Review the more detailed descriptions of typical wastes to determine which waste streams actually result from your activities.
3. If you determine that you actually do generate a particular waste stream, report the four-digit EPA Hazardous Waste Number in Item X of Form 8700-12, "Notification of Hazardous Waste Activity."

The specific instructions for completing Item X (Description of Hazardous Wastes) of the notification form are included in the notification package. You should note, however, that specific EPA Hazardous Waste Numbers beginning with:

- ▶ "F" should be entered in Item X, Section A.
- ▶ "K" should be entered in Item X, Section B.
- ▶ "P" or "U" should be entered in Item X, Section C.
- ▶ "D" should be entered in Item X, Section E.

The industries and waste streams described here do not provide a comprehensive list, but rather serve as a guide to potential small quantity generators in determining which of their wastes, if any, are hazardous. Except for the pesticide and wood preserving categories, this Appendix does not include EPA Hazardous Waste Numbers for commercial chemical products that are hazardous when discarded unused. These chemicals and their EPA Hazardous Waste Numbers are listed in Title 40 of the Code of Federal Regulations (40 CFR) in Section 261.33.

If the specific EPA Hazardous Waste Number that should be applied to your waste stream is unclear, please refer to 40 CFR Part 261, reprinted in the Notification Form 8700-12 package. In those cases where more than one EPA Hazardous Waste Number is applicable, all should be used. If you have any questions, or if you are unable to determine the proper EPA Hazardous Waste Numbers for your wastes, contact your state hazardous waste management agency, or the RCRA/ Superfund Hotline (see Appendix A).

Solvents:

Solvents, spent solvents, solvent mixtures, or solvent still bottoms are often hazardous. This includes solvents used in degreasing (identified as F001) and paint brush cleaning and distillation residues from reclamation. The following are some commonly used hazardous solvents (also see ignitable wastes for other hazardous solvents, and 40 CFR 261.31 for most listed hazardous waste solvents):

Benzene	F005
Carbon Disulfide	F005
Carbon Tetrachloride	F001
Chlorobenzene	F002
Cresols	F004
Cresylic Acid	F004
O-Dichlorobenzene	F002
Ethanol	D001
2-Ethoxyethanol	F005
Ethylene Dichloride	D001
Isobutanol	F005

APPENDIX B

Isopropanol	D001
Kerosene	D001
Methyl Ethyl Ketone	F005
Methylene Chloride	F001
	F002
Naphtha	D001
Nitrobenzene	F004
2-Nitropropane	F005
Petroleum Solvents	D001
(Flashpoint less than 140°F)	
Pyridine	F005
1,1,1-Trichloroethane	F001
	F002
1,1,2-Trichloroethane	F002
Tetrachloroethylene	
(Perchloroethylene)	F001
	F002
Toluene	F005
Trichloroethylene	F001
	F002
Trichlorofluoromethane	F002
Trichlorotrifluoroethane	
(Valclene)	F002
White Spirits	D001

Acids/Bases:

Acids, bases, or mixtures having a pH less than or equal to 2 or greater than or equal to 12.5, are considered corrosive (for a complete description of corrosive wastes, see 40 CFR 261.22, Characteristic of corrosivity). All corrosive materials and solutions have the EPA Hazardous Waste Number D002. The following are some of the more commonly used corrosives:

Acetic Acid	Nitric Acid
Ammonium Hydroxide	Oleum
Chromic Acid	Perchloric Acid
Hydrobromic Acid	Phosphoric Acid
Hydrochloric Acid	Potassium Hydroxide
Hydrofluoric Acid	Sodium Hydroxide
	Sulfuric Acid

Dry Cleaning Filtration Residues:

Cooked powder residue (perchloroethylene plants only), still residues, and spent cartridge filters containing perchloroethylene or valclene are hazardous and have the EPA Hazardous Waste Number F002.

Still residues containing petroleum solvents with a flashpoint less than 140°F are considered hazardous and have the EPA Hazardous Waste Number D001.

Heavy Metals/Inorganics:

Heavy metals and other inorganic waste materials exhibit the characteristic of EP Toxicity and are considered hazardous if the extract from a representative sample of the waste has any of the specific constituent concentrations as shown in 40 CFR 261.24, Table 1. This may include dusts, solutions, wastewater treatment sludges, paint wastes, waste inks, and other such materials which contain heavy metals/inorganics (note that wastewater treatment sludges from electroplating operations are identified as F006). The following are EP Toxic:

Arsenic	D004
Barium	D005
Cadmium	D006
Chromium	D007
Lead	D008
Mercury	D009
Selenium	D010
Silver	D011

Ignitable Wastes:

Ignitable wastes include any liquids that have a flashpoint less than 140°F, any non-liquids that are capable of causing a fire through friction, absorption of moisture, or spontaneous chemical change, or any ignitable compressed gas as described in 49 CFR 173.300 (for a complete

description of ignitable wastes, see 40 CFR 261.21, Characteristic of ignitability). Examples are spent solvents (see also solvents), solvent still bottoms, ignitable paint wastes (paint removers, brush cleaners and stripping agents), epoxy resins and adhesives (epoxies, rubber cements and marine glues), and waste inks containing flammable solvents. Unless otherwise specified, all ignitable wastes have the EPA Hazardous Waste Number of D001.

Some commonly used ignitable compounds are:

Acetone	F003
Benzene	F005
n-Butyl Alcohol	F003
Chlorobenzene	F002 ¹
Cyclohexanone	F003
Ethyl Acetate	F003
Ethylbenzene	F003
Ethyl Ether	F003
Ethylene Dichloride	D001
Methanol	F003
Methyl Isobutyl Ketone	F003
Petroleum Distillates	D001
Xylene	F003

Ink Sludges Containing Chromium and Lead:

This includes solvent washes and sludges, caustic washes and sludges, or water washes and sludges from cleaning tubs and equipment used in the formulation of ink from pigments, driers, soaps, and stabilizers containing chromium and lead. All ink sludges have the EPA Hazardous Waste Number K086.

¹Chlorobenzene is listed by EPA as a hazardous waste due to its toxicity and has been assigned EPA Hazardous Waste Number F002. It has a flashpoint, however, of less than 140°F and is therefore included here as an ignitable waste.

Lead-Acid Batteries:

Used lead-acid batteries should be reported on the notification form *only* if they are not recycled. Used lead-acid batteries that *are* recycled do not need to be counted in determining the quantity of waste that you generate per month, nor do they require a hazardous waste manifest when shipped off your premises. (Note: Special requirements do apply if you recycle your batteries on your own premises—see 40 CFR Part 266.)

Lead Dross	D008
Spent Acids	D002
Lead-Acid Batteries	D008

Pesticides:

The pesticides listed below are hazardous. Wastes marked with an asterisk (*) have been designated acutely hazardous. For a more complete listing, see 40 CFR 261.32 and 261.33 for specific listed pesticides, and other wastes, wastewaters, sludges, and by-products from pesticide formulators. (Note that while many of these pesticides are no longer in common use, they are included here for those cases where they may be found in storage.)

* Aldicarb	P070
* Aldrin	P004
Amitrole	U011
* Arsenic Pentoxide	P011
* Arsenic Trioxide	P012
Cacodylic Acid	U136
Carbamic Acid, Methylnitroso-, Ethyl Ester	U178
Chlordane	U036
* Copper Cyanides	P029
1,2-Dibromo-3-chloropropane	U066
1,2-Dichloropropane	U083
1,3-Dichloropropene	U084
2,4-Dichlorophenoxy Acetic Acid	U240
DDT	U061
* Dieldrin	P037
Dimethylcarbamoyl Chloride	U097

Pesticides (Continued):

*Dinitrocresol	P047
*Dinoseb	P020
Disodium Monomethanearsenate	D004
*Disulfoton	P039
*Endosulfan	P050
*Endrin	P051
Ethylmercuric Chloride	D009
*Famphur	P097
*Heptachlor	P059
Hexachlorobenzene	U127
Kepone	U142
Lindane	U129
2-Methoxy Mercuric Chloride	D009
Methoxychlor	D014
*Methyl Parathion	P071
Monosodium Methanearsenate	D004
*Nicotine	P075
*Parathion	P089
Pentachloronitrobenzene	U185
Pentachlorophenol	U242
Phenylmercuric Acetate	D009
*Phorate	P094
*Strychnine	P108
2,4,5-Trichlorophenoxy	
Acetic Acid	U232
2-(2,4,5-Trichlorophenoxy)-	
Propionic Acid	U233
*Thallium Sulfate	P115
Thiram	U244
*Toxaphene	P123
Warfarin	U248

Reactives:

Reactive wastes include reactive materials or mixtures which are unstable, react violently with or form explosive mixtures with water, generate toxic gases or vapors when mixed with water (or when exposed to pH conditions between 2 and 12.5 in the case of cyanide or sulfide bearing wastes), or are capable of detonation or explosive reaction when heated or subjected to shock (for a complete description of reactive wastes, see 40 CFR 261.23, Characteristic of reactivity). Unless

otherwise specified, all reactive wastes have the EPA Hazardous Waste Number D003. The following materials are commonly considered to be reactive:

Acetyl Chloride	Organic Peroxides
Chromic Acid	Perchlorates
Cyanides	Permanganates
Hypochlorites	Sulfides

Spent Plating and Cyanide Wastes:

Spent plating wastes contain cleaning solutions and plating solutions with caustics, solvents, heavy metals, and cyanides. Cyanide wastes may also be generated from heat treatment operations, pigment production, and manufacturing of anti-caking agents. Plating wastes are generally Hazardous Waste Numbers F006-F009, with F007-F009 containing cyanide. Cyanide heat treating wastes are generally Hazardous Waste Numbers F010-F012. See 40 CFR 261.32 for a more complete description of plating wastes.

Wood Preserving Agents:

The wastewater treatment sludges from wastewater treatment operations are considered hazardous (EPA Hazardous Waste Number K001—bottom sediment sludges from the treatment of wastewater processes that use creosote and pentachlorophenol). In addition, unless otherwise indicated, specific wood preserving compounds are:

Chromated Copper Arsenate	D004
Creosote	U051
Pentachlorophenol	F027



ACKNOWLEDGEMENT OF NOTIFICATION OF HAZARDOUS WASTE ACTIVITY

This is to acknowledge that you have filed a Notification of Hazardous Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act (RCRA). Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.

EPA I.D. NUMBER

• ILD069503944

E AND L TANK CLEANERS INC

PI BOX 41

PECTONE

IL

60468

INSTALLATION ADDRESS

S RATHJF RD

PECTONE

IL

60468

EPA Form 8700-12A (4-80)

This notification was applied for and issued to Ernest and Lorraine Winkle, who are the owners of Custom Blended Oils Inc. The E. & L. Tank Cleaners name has been changed to Custom Blended Oils Inc. and notification of the change was made to the Illinois E.P.A. on April 20, 1988. The correspondence from Lawrence W. Eastep is attached.



ACKNOWLEDGEMENT OF NOTIFICATION
OF HAZARDOUS WASTE ACTIVITY
(VERIFICATION)

This is to acknowledge that you have filed a Notification of Hazardous Waste Activity for the installation located at the address shown in the box below to comply with Section 3010 of the Resource Conservation and Recovery Act (RCRA). Your EPA Identification Number for that installation appears in the box below. The EPA Identification Number must be included on all shipping manifests for transporting hazardous wastes; on all Annual Reports that generators of hazardous waste, and owners and operators of hazardous waste treatment, storage and disposal facilities must file with EPA; on all applications for a Federal Hazardous Waste Permit; and other hazardous waste management reports and documents required under Subtitle C of RCRA.

EPA I.D. NUMBER

•ILD069503944

E AND L TANK CLEANERS INC
PO BOX 41
PEOTONE

IL 60468

INSTALLATION ADDRESS

S RATHJE RD
PEOTONE

IL 60468

m 3/19/86

EPA		U.S. ENVIRONMENTAL PROTECTION AGENCY	
NOTIFICATION OF HAZARDOUS WASTE ACTIVITY			
I. NAME OF INSTALLATION		II. INSTALLATION MAILING ADDRESS	
III. LOCATION OF INSTALLATION		IV. INSTALLATION CONTACT	
V. OWNERSHIP		VI. TYPE OF HAZARDOUS WASTE ACTIVITY	
VII. MODE OF TRANSPORTATION		VIII. FIRST OR SUBSEQUENT NOTIFICATION	
IX. DESCRIPTION OF HAZARDOUS WASTES		C. INSTALLATION'S EPA I.D. NO.	

RECEIVED
JAN 24 1986
PLEASE PLACE LABEL IN THIS SPACE
U.S. EPA, REGION V
C231-5

FOR OFFICIAL USE ONLY

COMMENTS

INSTALLATION'S EPA I.D. NUMBER
F1LD069503944

APPROVED
A

DATE RECEIVED
(yr. mo. & day)
860124

I. NAME OF INSTALLATION
E & L TANK CLEANERS, INC.

II. INSTALLATION MAILING ADDRESS

STREET OR P.O. BOX
PO BOX 41

CITY OR TOWN
PEOTONE

ST.
ILLINOIS

ZIP CODE
60468

III. LOCATION OF INSTALLATION

STREET OR ROUTE NUMBER
SOUTH RATHJE ROAD

CITY OR TOWN
PEOTONE

ST.
ILLINOIS

ZIP CODE
60468

IV. INSTALLATION CONTACT

NAME AND TITLE (last, first, & job title)
WINKLE ERNEST PRESIDENT

PHONE NO. (area code & no.)
312 821 4747

V. OWNERSHIP

A. NAME OF INSTALLATION'S LEGAL OWNER
ERNEST WINKLE

B. TYPE OF OWNERSHIP
(enter the appropriate letter into box)
F - FEDERAL
M - NON-FEDERAL

VI. TYPE OF HAZARDOUS WASTE ACTIVITY (enter "X" in the appropriate box(es))

GENERATION
A. PRIMARY
B. SECONDARY
C. TERTIARY
D. UNDERGROUND STORAGE TANK

VII. MODE OF TRANSPORTATION (transporters only - enter "X" in the appropriate box(es))

VIII. FIRST OR SUBSEQUENT NOTIFICATION
Mark "X" in the appropriate box to indicate whether this is your first notification or subsequent notification.
If this is not your first notification, enter your last notification date in the space provided.

IX. DESCRIPTION OF HAZARDOUS WASTES

C. INSTALLATION'S EPA I.D. NO.

IX. DESCRIPTION OF HAZARDOUS WASTES (continued from front)

A. HAZARDOUS WASTES FROM NON-SPECIFIC SOURCES. Enter the four-digit number from 40 CFR Part 261.31 for each listed hazardous waste from non-specific sources your installation handles. Use additional sheets if necessary.

1 F 0 3 0	2	3	4	5	6
7	8	9	10	11	12

B. HAZARDOUS WASTES FROM SPECIFIC SOURCES. Enter the four-digit number from 40 CFR Part 261.32 for each listed hazardous waste from specific industrial sources your installation handles. Use additional sheets if necessary.

13	14	15	16	17	18
19	20	21	22	23	24
25	26	27	28	29	30

C. COMMERCIAL CHEMICAL PRODUCT HAZARDOUS WASTES. Enter the four-digit number from 40 CFR Part 261.33 for each chemical substance your installation handles which may be a hazardous waste. Use additional sheets if necessary.

31	32	33	34	35	36
37	38	39	40	41	42
43	44	45	46	47	48

D. LISTED INFECTIOUS WASTES. Enter the four-digit number from 40 CFR Part 261.34 for each listed hazardous waste from hospitals, veterinary hospitals, medical and research laboratories your installation handles. Use additional sheets if necessary.

49	50	51	52	53	54
----	----	----	----	----	----

E. CHARACTERISTICS OF NON-LISTED HAZARDOUS WASTES. Mark "X" in the boxes corresponding to the characteristics of non-listed hazardous wastes your installation handles. (See 40 CFR Parts 261.21 - 261.24.)

- ☐ 1. IGNITABLE (D001)
 ☐ 2. CORROSIVE (D002)
 ☐ 3. REACTIVE (D003)
 ☐ 4. TOXIC (D004)

X. CERTIFICATION

I certify under penalty of law that I have personally examined and am familiar with the information submitted in this and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment.

SIGNATURE

NAME & OFFICIAL TITLE (type or print)

DATE SIGNED

Ernest Winkle

ERNEST WINKLE, PRESIDENT

1/14/86



Illinois Environmental Protection Agency 2200 Churchill Road, Springfield, IL 62706

217/782-6762

Refer to: 1970750002 -- Will County
Custom Blended Oil
Log 1988-12


April 20, 1988

Custom Blended Oil, Inc.
ATTN: Ernest Winkel
Post Office Box 1040
Peotone, Illinois 60468

Gentlemen:

This letter is to inform you that the Agency has revised your Development and Operating permit to show change in company name.

Very truly yours,


Lawrence W. Eastep, P.E., Manager
Permit Section
Division of Land Pollution Control

LWE:ML:jas/1081j,100

cc: Division File
Northern Region
Compliance



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 5

230 SOUTH DEARBORN ST.

CHICAGO, ILLINOIS 60604

REPLY TO THE ATTENTION OF:

5HE-12

APR 17 1987

Mr. Ernest Winkle
E & L Tank Cleaners
P.O. Box 41
Peotone, IL 60468

EPA ID Number: ILD-069-503-944

Re: Requirements for Generators,
Marketers and Burners of
Hazardous Waste and Used
Oil Fuels

Dear Mr. Winkle:

This letter acknowledges that the United States Environmental Protection Agency (U.S. EPA) has received your Notification of Hazardous Waste Activity as required by the new Waste-As-Fuel regulations. These regulations were published in the November 29, 1985, Federal Register and apply to persons who generate, market, transport, or burn hazardous waste fuel or used oil fuel.

The following information highlights the administrative requirements for persons subject to the current Waste-As-Fuel regulations promulgated on November 29, 1985, in 40 CFR (Code of Federal Regulations) Part 266, Subparts D and E.

GENERATORS

Persons Generating Hazardous Waste Fuel. Generators that send their hazardous waste to a hazardous waste fuel marketer are subject to the 40 CFR Part 262 generator standards [see 40 CFR 266.32(a)]. Generators that market their hazardous waste fuel directly to burners are subject to both the 40 CFR Part 262 standards and the hazardous waste fuel marketer requirements [see 40 CFR 266.32(b)]. Generators that are burners are also subject to 40 CFR 266.35.

Persons Generating Used Oil Fuel. Used oil generators are exempt from the current Waste-As-Fuel regulations unless they: (1) market off-specification used oil fuel directly to a burner, or (2) burn off-specification used oil for energy recovery. Generators marketing directly to a burner are subject to 40 CFR 266.43. Generators burning off-specification used oil fuel are subject to 40 CFR 266.44.

MARKETERS

Persons Marketing Hazardous Waste Fuel. Persons who market hazardous waste fuel include the following: (1) generators marketing hazardous waste fuel directly to a burner, (2) persons who receive hazardous waste from generators and produce, process, or blend hazardous waste fuel, and (3) persons who distribute but do not process or blend hazardous waste fuel. Hazardous waste fuel marketers are required to have notified U.S. EPA of their hazardous waste fuel activities, have a U.S. EPA Identification Number, and market only to persons who have notified U.S. EPA and who burn the fuel only in industrial furnaces, industrial boilers, or utility boilers. These marketers are also required to comply with manifest requirements, certification of compliance with burning standards, recordkeeping requirements, and storage standards [see 40 CFR 266.34].

Persons Marketing Used Oil Fuel. 40 CFR 266.43 describes to whom the regulations for used oil marketing apply. The same requirements for persons marketing hazardous waste fuel apply to off-specification used oil fuel marketers, except for the manifest and storage requirements [see 40 CFR 266.43].

TRANSPORTERS

Persons Transporting Hazardous Waste Fuel. Persons who transport hazardous waste fuel are subject to the 40 CFR Part 263 standards for hazardous waste transporters. These persons are required to notify U.S. EPA of their Waste-As-Fuel activities. However, they are not required to renotify U.S. EPA of their hazardous waste transportation activities if they have already done so.

Persons Transporting Used Oil Fuel. Persons who transport used oil fuel, both on-specification and off-specification, are currently exempt from the Waste-As-Fuel regulations.


BURNERS

Persons Burning Hazardous Waste Fuel. Owners and Operators of industrial furnaces, industrial boilers and utility boilers that burn hazardous waste fuel are subject to the following: (1) notification to U.S. EPA of hazardous waste fuel activities, (2) manifest requirements, (3) certification with burner standards, (4) recordkeeping requirements, and (5) storage standards. Burners must also comply with the prohibitions on use in non-industrial boilers [see 40 CFR 266.35].

Persons Burning Used Oil Fuel. Owners and Operators of industrial furnaces, industrial boilers and utility boilers are subject to the same requirements as Hazardous Waste Fuel Burners except for the manifest and storage standards [see 40 CFR 266.44].

If you have any questions concerning this letter or the Waste-As-Fuel regulations, please contact either Ms. Shirlee Brauer at (312) 886-4591, or Ms. Laura Lodisio at (312) 886-7090 or the RCRA/Superfund Hotline at (800) 424-9436.

Sincerely,


Basil G. Constantelos, Director
Waste Management Division

Enclosure